

Rolls Royce Turbine Engines - Spey Series

---

**AD/RRT-S/14**

**LPT Stage 2 NGV Seal Support**

**10/99**

Applicability: Rolls Royce Spey 555-15, -15/10, -15H, -15H/10, -15N, -15N/12, -15N/20, -15P, -15P/12, and -15P/20 engines.

Requirement: Modify affected LPT Stage 2 NGV Seal Supports by incorporating Modification No 6421 in accordance with Rolls Royce Service Bulletin Sp72-1063.

*Note: CAA (UK) AD 007-05-99 also refers.*

Compliance: No later than 30 June 2003.

This Airworthiness Directive becomes effective on 7 October 1999.

Background: Heavy rubbing can occur between the LP turbine stage 2 nozzle guide vane support ring seal assembly and the LP turbine discs seals. In extreme cases the disc drive arms can be damaged.