

AlliedSignal (Garrett/AiResearch) Turbine Engines - TPE 331 Series

AD/TPE 331/30
Amdt 2

Fuel Pump Drive Shaft

4/88

Applicability: TPE 331 models as listed in Garrett Service Bulletin TPE 331-73-0121 Rev 5.

Requirement: Garrett Service Bulletin TPE 331-73-0121 Rev 5.

Compliance: Unless already accomplished; in accordance with Requirement document Para D.

Note: Compliance with the previous issue of this Directive (SB TPE 334-73-0121 Rev 4) does not necessarily constitute compliance with this Directive - refer Rev 5 Accomplishment Instruction Section 2.

Background: This Directive is amended to reflect GTEC SB TPE 331-73-0121 Rev 5 which deletes engine models, corrects a part number and adds reference to SB 73-0156 and a hazardous material warning.