

AlliedSignal (Garrett/AiResearch) Turbine Engines - TPE 331 Series

AD/TPE 331/34

Beryllium Spectrometric Oil Analysis

9/88

CANCELLED.

Background: Revision 1 to GTEC SB TPE 331-72-0530 cancels the requirement to 'SOAP' check for beryllium as the inspection has not proved completely effective in detecting beryllium copper nut erosion. This Directive is therefore cancelled.