

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/AC/19.

---

### **Twin Commander (Gulfstream/Rockwell/Aerocommander 500, 600 and 700) Series Aeroplanes**

**AD/AC/19**                      **Throttle Control Rod Ends - Inspection and Replacement**                      **8/2008**

Requirement:      CANCELLED.

This AD is cancelled on 31 July 2008.

Background:      This unique Australian AD, raised in 1961 against Aero Design (also known as Aero Commander) Service Bulletin (SB) No. 74A, required inspection of throttle control rod ends and replacement of aluminium control rods ends with ones manufactured from steel.

Compliance was forthwith.

As all affected aircraft would have been modified by now, this AD is considered to be no longer required.



James Coyne  
Delegate of the Civil Aviation Safety Authority

13 June 2008