

Twin Commander (Gulfstream/Rockwell/ Aerocommander 500, 600 and 700) Series Aeroplanes

---

**AD/AC/58  
Amdt 2**

**Elevator Control System Bob Weight  
Installation - Inspection and Modification**

**3/82**

CANCELLED

Requirement: The requirements of AD/AC/58 Amdt 2 are now consolidated into AD/AC/56Amdt 3.

Background: Cracks have been found in the bob weight side supports of six overseas registered aeroplanes. Effectivity has been extended by aircraft serial number.