COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

Beechcraft 60 (Duke) Series Aeroplanes

AD/BEECH 60/38 Air Conditioning Compressor Pulley 4/83 Guard and Retaining Bolt

Applicability: All models 60, A60 and B60 with S/Nos. P-4 to P-577, P-579 to P-587 and P-589 and

P-592.

Requirement: Action in accordance with Beechcraft SI No. 1236.

Compliance: Within 100 hours time in service after 30 May 1983.

Background: The installation of a compressor pulley guard is considered mandatory by the

manufacturer to reduce the possibility of the clutch coming in contact with a fuel line.