

Beechcraft 90 and 65-90 (King Air) Series Aeroplanes

---

**AD/BEECH 90/14**                      **Elevator Tab Hinge Beam - Inspection**                      **7/68**

Applicability:    All models in excess of 1000 hours total time in service.

Requirement:    Inspect the upper and lower flanges of the LH and RH elevator tab hinge beam P/N 50-610000-94 for cracking along the rivet line.

Compliance:    Forthwith and thereafter at intervals not exceeding 200 hours time in service.