

Beechcraft 90 and 65-90 (King Air) Series Aeroplanes

**AD/BEECH 90/41 Cabin Heater Modification and Aft Fuselage
Drainage and Sealing - Modification 2/76**

Applicability: Models 65-90, 65-A90 & B90 with S/Nos. LJ-1 to LJ-484.

- Requirement: 1. Install a temporary placard on the heater control panel stating:
- “IF HEATER FAILS TO HEAT, TURN OFF IMMEDIATELY”
2. Modify cabin heater installation, including the fitment of a cabin heater out light,
 in accordance with Beechcraft SI No. 0230-412, Revision 3.
3. Modify the aft fuselage in accordance with Beechcraft SI No. 0268-103, Rev. 1.

Compliance: For Para. 1 - Within 50 hours time in service after 27 Feb. 1976.

 For Para. 2 - Before 1 January 1977.

 For Para. 3 - Within 100 hours time in service after 27 Feb. 1976.

Note: Temporary placard, para. 1, may be removed when para. 2 is accomplished.