

Pilatus Britten-Norman BN-2 Series Aeroplanes

---

**AD/BN-2/24  
Amdt 1**

**Flap Attachments and Flap  
Operating Lever - Inspection**

**3/73**

Applicability: All models not incorporating Britten Norman Mod. NB/M/417.

Document: Britten Norman SB No. BN-2/SB.36 Issue 3.

Compliance: Within 100 hours time in service after 30 March 1973 unless already accomplished.