

DHC-6 (Twin Otter) Series Aeroplanes

AD/DHC-6/63

Gust Lock Assembly

3/90 DM

Applicability: S/Nos 1 to 690, 692, 693, 695 and 696.

Requirement: Action in accordance with Boeing Canada SB 6/508.

Note: Canadian AD CF-90-01 refers.

Compliance: Prior to 31 July 1990.

Background: Three instances have been reported where aircraft took off with pre-mod 6/1676 gust locks still engaged.