

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/EMB-110/19.

---

### Embraer EMB-110 (Bandeirante) Series Aeroplanes

**AD/EMB-110/19**

**Fire Extinguishing System - Wire  
Disconnection**

**13/2008**

Requirement: CANCELLED.

This AD is cancelled on 18 December 2008.

Background: This unique Australian AD was raised in 1982 against Embraer Service Bulletin (SB) No. 110-26-005 required disconnection of redundant wiring installed in the engine compartment that in the event of insulation loss may cause a short circuit rendering the fire extinguisher system inoperative.

Compliance was within 100 hours TIS after 30 November 1982.

As all affected aircraft would have been modified by now, this AD is considered to be no longer required.



James Coyne  
Delegate of the Civil Aviation Safety Authority

6 November 2008