

Embraer EMB-110 (Bandeirante) Series Aeroplanes

AD/EMB-110/21 **Fuel Filter Drain Hose - Replacement** **2/83**

Applicability: All models EMB-110.

Document: Embraer SB No. 110-28-024.

Note: Brazilian CTA AD 82-10-01 refers.

Compliance: Within 100 hours time in service after 28 February, 1983.

Background: Existing fuel filter drain hoses are to be replaced with rigid tubes in order to minimise the possibility of failure. Such a failure could lead to the draining of the aircraft fuel tanks.