

Fuji FA-200 Series Aeroplanes

AD/FA-200/25

Horizontal Stabiliser Forward Spar

2/92

CANCELLED.

Background: The CAA has been advised by the manufacturer that the problem of cracking of the spar web should be confined to early production aircraft. Aircraft with serial numbers 12 and subsequent were fitted with a reinforcing doubler which should prevent the cracking. The only early aircraft on the Australian register has been similarly modified, so there is no longer any need for the inspection requirements of this AD.