

Airparts (NZ) Ltd. FU 24 Series Aeroplanes

AD/FU24/12

Rudder Lowr Rib - Inspection

6/68

Applicability: All models not incorporating James Aviation Mod. HA/FU24/116.

Requirement: Detach the torque tube from the rudder and examine the rudder lower rib assembly P/N 242406 at the attachment of the rudder torque tube flange P/N 242410 for cracking and corrosion.

Compliance: At intervals not exceeding 500 hours time in service.