

Airparts (NZ) Ltd. FU 24 Series Aeroplanes

---

**AD/FU24/40**

**Cockpit Ventilators - Modification**

**4/71**

Applicability: Model FU24-950 and other FU24 Series aeroplanes fitted with Mod. AP55 Part A with cockpit ventilators to Mod. AP23 or similarly located air intakes.

Requirement: Seal off subject cockpit ventilators.

Compliance: Within 50 hours time in service after 19 April 1971.