

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/FU24/61.

---

### Airparts (NZ) Ltd. FU 24 Series Aeroplanes

**AD/FU24/61**

**Main Landing Gear Torque Link  
Brackets - Inspection/Replacement**

**5/2009**

Requirement: CANCELLED.

This AD is cancelled on 7 May 2009.

Background: This unique Australian AD, issued in 1983, required replacement of main landing gear torque link brackets that were subject to incorrect heat treatment. The AD compliance was within 100 hours time in service after 31 July 1983. As all torque link brackets would have been replaced by now, the AD is no longer required.



David Villiers  
Delegate of the Civil Aviation Safety Authority

26 March 2009