

Gulfstream (Grumman American) GA-7 Series Aeroplanes

AD/GA-7/3

**Elevator Bellcrank Pivot Bolt - Inspection
and Replacement**

NK

Applicability: All models GA-7 with S/Nos. GA7-00002, 0005 to 0021.

Document: Gulfstream American SB No. ME-3.

- Compliance:
1. Inspect within 100 hours time in service after 31 March 1979 and thereafter at intervals not exceeding 100 hours time in service.
 2. Replace within 500 hours time in service after 31 March 1979.