

Gulfstream (Grumman American) GA-7 Series Aeroplanes

AD/GA-7/7

Fuel Line Chafing - Inspection

NK

Applicability: Model GA-7 with S/Nos. GA-7-0001 to GA-7-0076.

Document: 1. GAC SB No. ME-14; or
2. FAA AD 79-05-06 amendment 39-3423.

Compliance: Within 25 hours time in service after 9 April 1979.

Background: The main fuel line aft of the left hand engine firewall may be chafed by the propeller control cable.