COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

Grob G115 Series Aeroplanes

AD/GROB 115/2 Engine Control Cables and Fuel Shut-Off Valve 12/89

Applicability: All Grob G115 series aircraft, except those already modified as listed in Grob SB

TM1078-8.

Requirement: Action in accordance with Grob Service Bulletin TM1078-8.

Note: LBA AD 89-141 Grob refers.

Compliance: Prior to 31 January 1990.

Background: To maintain aircraft airworthiness, replacement of the engine control cables and fuel

shut-off valve insert is required.