

Consolidated Aeronautics, Colonial and LA-4 Series Aeroplanes

AD/LA-4/9

Rudder Bellcrank - Inspection

3/74

Applicability: All models.

Document: Consolidated Aeronautics SL L-50.

Compliance: Within 100 hours time in service after 30 April 1974, and there- after at intervals not exceeding 1 year or at anytime rudder pedals are subjected to abnormal loads.