

Aerospatiale Rallye Series Aeroplanes

---

**AD/MSR/10**

**Firewall Sealing - Modification**

**10/70**

Applicability: All models 880B, 885, 893A and 894A.

Requirement: 1. Replace the existing firewall sealant with a fireproof sealant; or  
2. FAA AD 70-17-6.

Compliance: Within 100 hours time in service after 30 October 1970.