

Mitsubishi MU-2 Series Aeroplanes

AD/MU-2/13

**Main Landing Gear Forward Door
Emergency Cable - Inspection**

11/75

Applicability: All models MU-2B-30 with S/Nos. 502 to 547, and MU-2B-35 with S/Nos. 501 and 548 to 615. Not fitted with Cable P/N 030A-38558-41/51.

Document: Mitsubishi SB No. 170.

Compliance: Within 100 hours time in service after 31 December 1975 and there- after at intervals not exceeding 100 hours time in service.