

Mitsubishi MU-2 Series Aeroplanes

---

**AD/MU-2/18**

**Flap Jack Screw - Inspection: Flap  
Gearbox - Inspection and Re-adjustment**

**3/77**

Applicability: Model MU-2B-10, -51, -20, -25 and -26 with S/Nos. 005 to 326. Model MU-2B-30, -35 and -36 with S/Nos. 501 to 672.

Document: Mitsubishi SB No. 167C.

Compliance: Within 100 hours time in service after 30 April 1977.