

Mitsubishi MU-2 Series Aeroplanes

---

**AD/MU-2/24**                      **Nose Landing Gear L/H Drag Strut Attach**                      **11/83**  
**Amdt 1**                              **Bracket - Inspection and Replacement**

Applicability: All models MU-2B-30/-35/-36 with S/Nos. 501 thru 696, excepting S/Nos. 652 and 661. All models MU-2B-35/-36A/-60 with S/Nos. 652SA, 661SA, 697SA through 799SA, 1501SA through 1553SA. 1555SA through 1562SA.

Document: 1. Mitsubishi SB No. 195. or  
2. Mitsubishi Aircraft International S.B. No. SBO 46/32-005 whichever is applicable.

*Note: JCAB AD No. TCD-2263-83 also refers.*

Compliance: Unless already accomplished:

1. Inspect within 100 hours time in service after 30 June 1983 for components with more than 1000 hours time in service.
2. Inspect within 100 hours time in service after component achieves 1000 hours time in service.
3. Replace with improved bracket P/No. 030A-31121-11 in accordance with requirement document.

Background: This Directive has been raised in issue to include additional aircraft model applicability and requirement document references.