

Mitsubishi MU-2 Series Aeroplanes

---

**AD/MU-2/57**

**Acrylic Windshield and Side Windows**

**6/96**

Applicability: MU-2B -10, -15, -20, -25, -26 S/N 008 to 347 (except 313 and 321), and -30, -35, -36, S/N 501 to 696 (except 652 and 661); equipped with windscreen, cockpit or cabin windows P/Nos:

010A-31450-1 or -2

010A-31451-1 or -2

010A-31874-1 or -2

010A-31870

010A-31870-11

030A-32402

Requirement: Inspect, and replace as necessary, in accordance with MHI MU-2 SB 224A.

*Note: JCAB AD TCD-4311-95 refers.*

Compliance: Within 100 hours time in service after 23 May 1996, thereafter at intervals not exceeding 100 hours time in service.

Background: This Directive is issued to prevent possible in-flight failure of the acrylic transparencies due to undetected cracking.