

Mitsubishi MU-2 Series Aeroplanes

AD/MU-2/58

Wing Tip Tank Attachment

8/96

- Applicability: Model MU-2B-10, -15, -20, -25, -26, with serial numbers 008 through 347 (except 313, 321).
Model MU-2B-30, -35, -36, with serial numbers 501 through 696 (except 652, 661).
- Requirement: Inspect the wing tip tank fitting attachment bolts in accordance with Mitsubishi Heavy Industry MU-2 Service Bulletin 225.
Note: JCAB TCD-4310-96 refers.
- Compliance: Within 100 hours time in service after 18 July 1996.
- Background: Incorrect wing tip attachment bolts have been found corroded. Failure of corroded bolts could result in the separation of the wing tip tank from the aircraft.