COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

Mitsubishi MU-2 Series Aeroplanes

AD/MU-2/64 Elevator Trim Indication 12/98

Applicability: Model MU-2B-10, -15, -20, -25 and -26 aeroplanes with serial numbers (S/N) 008

through 347 (except S/N 313 and 321); and model MU-2B-30, -35 and -36 aeroplanes

with S/N 501 through 696 (except S/N 652 and 661).

Requirement: Modify the elevator trim indicator scale dial in accordance with Mitsubishi Heavy

Industries Service Bulletin No 228 dated 13 July 1998.

Note: JCAB TCD-3740A-98 refers.

Compliance: Within 100 hours time in service from the effective date of this directive.

This Airworthiness Directive becomes effective on 5 November 1998.

Background: AD/MU-2/52, issued in 1993, mandated the modification of the autopilot to reduce

nose-down trim range. This directive requires the modification of the elevator trim

indicator scale to be consistent with the available range of the elevator trim.