COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

Partenavia P68 Series Aeroplanes

AD/P68/21 Horizontal Stabilator to Fuselage Frame 4/83
Attachment - Check Torque

Applicability: All Partenavia P68, P68B, P68C, P68C-TC and P68 Observer aircraft with S/Nos. 1

to 289 except S/Nos. 234, 256, 259, 269 and 288.

Requirement: Check torque AN4-6A bolts securing the horizontal stabilator torque tube brackets to

fuselage frame. If necessary retorque to correct torque value 78-83 LB inches.

Note: RAI AD 83-3 and Partenavia SB No. 57 refer.

Compliance: Before further flight.