

Partenavia P68 Series Aeroplanes

AD/P68/29
Amdt 1

Elevator Trim Tab

1/89

Applicability: All P68 up to serial number 381 included.

Requirement: Action in accordance with Partenavia SB 73 Rev 1.

Note: RAI AD 88-167 refers.

Compliance: Within 100 hours time in service after 20 July 1988.

Background: To reduce the flexibility of stabilator tabs with seven ribs or eight ribs, modification or replacement is required. This will increase control authority. Amendment 1 calls up Rev 1 of the Requirement document which may alleviate the action required for aircraft with more than 3500 hours T.I.S.