

Partenavia P68 Series Aeroplanes

AD/P68/40 Stabilator Torque Tube Attachment Shelves, 5/94
Flap and Aileron Hinge Shelves

Applicability: All Model P68 aircraft.

Requirement: Action in accordance with Partenavia Mandatory Service Bulletin 91.

Note: RAI AD 94-026 refers.

Compliance: At the next 100 hour inspection after 28 April 1994, and thereafter at intervals not to exceed one calendar year.

Background: A case of corroded shelves was reported to the manufacturer.