

Piper PA-20 (Pacer) Series Aeroplanes

**AD/PA-20/7
Amdt 1**

**Fuselage Fabric in Area of Wind Shield Top
Attachment Channel - Modification**

4/69

Applicability: All models not incorporating SL 362.

Document: 1. Piper SB No 174; or
2. FAA AD 61-6-6.

Compliance: At intervals not exceeding 100 hours time in service or 6 months whichever occurs first.