

Piper PA-20 (Pacer) Series Aeroplanes

---

**AD/PA-20/14      Fire Hazard Prevention - Inspection and Rework      4/85  
DM**

Applicability: All models.

Requirement: Piper SB No 161A.

*Note: FAA AD 57-22-1 refers.*

Compliance: Within 25 hours time-in-service after 31 March 1985 and thereafter at intervals not exceeding 100 hours.

Background: Following an in-flight fire it has been considered necessary to re-issue the requirements of cancelled AD/PA-20/4.