

Piper PA-22 (Tri-Pacer and Colt) Series Aeroplanes

---

**AD/PA-22/13  
Amdt 1**

**Fuselage Fabric in Area of Windshield Top  
Attachment Channel - Inspection**

**5/69**

Applicability: All models not incorporating SL 362.

Document: 1. Piper SB No. 174; or  
2. FAA AD 61-6-6.

Compliance: At intervals not exceeding 100 hours time in service or 6 months whichever occurs first.