

Piper PA-22 (Tri-Pacer and Colt) Series Aeroplanes

AD/PA-22/31 Fire Hazard Prevention - Inspection and Rework 4/85 DM

Applicability: All models.

Requirement: Piper SB 161A.

Note: FAA AD 57-22-1 refers.

Compliance: Within 25 hours time-in-service after 31 March 1985 and thereafter at intervals not exceeding 100 hours.

Background: Following an in-flight fire it has been considered necessary to re-issue the requirements of cancelled AD/PA-22/10.