

Piper PA-23 (Apache and Aztec) Series Aeroplanes

---

**AD/PA-23/51**  
**Amdt 1**

**Landing Gear Selector Lever - Inspection**

**3/79**

Applicability: All models PA-23, PA-23-235 and PA-23-250 unless fitted with landing gear selector lever P/N 761-213.

Requirement: Inspect landing gear lever P/N 752-303 for cracks in the vicinity of the two right-angle bends. Where adhesive tape has been used to secure the warning light wires to the lever, the tape shall not be replaced over the area between the bends.

*Note: Piper SB No. 635 refers to this subject.*

Compliance: At intervals not exceeding 100 hours time in service.