

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-23/64.

---

### Piper PA-23 (Apache and Aztec) Series Aeroplanes

**AD/PA-23/64**

**Caution Placard - Flight Director or  
AFCS Flux Sensor - Installation**

**2/2009**

Requirement: CANCELLED.

This AD is cancelled on 12 February 2009.

Background: This unique Australian AD specified installation of a placard warning against carrying metallic objects on the rear baggage compartment hat shelf. The flux sensor for the Altimatic V Flight Director automatic flight control system is located near the hat shelf. Compliance with Piper SB No. 404 was required within 200 hours time in service after July 1974. The AD is no longer required.



James Coyne  
Delegate of the Civil Aviation Safety Authority

23 December 2008