

Piper PA-23 (Apache and Aztec) Series Aeroplanes

AD/PA-23/85

Hydraulic Hose Inspection

6/86 DM

Applicability:	PA-23-150/160 Apache S/Nos. 23-1 to 23-2046 PA-23-235 Apache S/Nos. 27-505 to 27-622 PA-23-250 Aztec S/Nos. 27-1 to 27-8154030.
Requirement:	Action in accordance with Piper Service Bulletin No. 822.
Compliance:	Within 10 hours time in service after 19 May 1986.
Background:	A group of hydraulic hoses were manufactured using material that does not meet the pressure requirements for operation in the aircraft hydraulic system.