
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-28/41.

Piper PA-28 Series Aeroplanes

AD/PA-28/41 Rapid Throttle Movement - Warning Placard 6/2008

Requirement: CANCELLED.

This AD is cancelled on 5 June 2008.

Background: This Directive specified installation of a cockpit placard prohibiting rapid opening of the throttle. This Directive was based on USA Directive 72-24-02. This Directive and 74-24-02 required compliance in 1973 so the unsafe condition no longer exists.



James Coyne
Delegate of the Civil Aviation Safety Authority

24 April 2008