

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-28/47.

---

### Piper PA-28 Series Aeroplanes

**AD/PA-28/47**

**Automatic Pilot Roll Servo  
Shear Pin - Installation**

**6/2008**

Requirement: CANCELLED.

This AD is cancelled on 5 June 2008.

Background: This Directive specified mandatory modification of any autopilot in accordance with Piper SL No. 695 or Edo-Aire Mitchell SL ML38 within 200 hours from September 1974. Therefore the unsafe condition no longer exists.



James Coyne  
Delegate of the Civil Aviation Safety Authority

22 April 2008