

Piper PA-28 Series Aeroplanes

AD/PA-28/78

**Fuel Tank Vent and Vent
Hose - Modification and Replacement**

11/79

Applicability: Model PA-28-161 with S/Nos. 28-7816024 to 28-7916475.
Model PA-28-181 with S/Nos. 28-7890023 to 28-7990493.
Model PA-28-201T with S/Nos. 28-7921001 to 28-7921068.
Model PA-28-201 with S/Nos. 28R-7737135 to 28R-7837317.
Model PA28RT-201 with S/Nos. 28R-7918001 to 28R-7918172.
Model PA28R-201T with S/Nos. 28R-7703309 to 28R-7803373.
Model PA28RT-201T with S/Nos. 28R-7931001 to 28R-7931222.
Model PA-28-235 with S/Nos. 28-7710079 to 28-7710089.
Model PA-28-236 with S/Nos. 28-7911001 to 28-7911204.

Document: Piper SB No. 646.

Compliance: Within 100 hours time in service after 30 November 1979.

Background: The fuel vent hose material fitted to these aircraft has proved unsuitable in service and may result in leakage of fuel and accumulation of fumes in the wing areas.