

Piper PA-28 Series Aeroplanes

AD/PA-28/79

Exhaust Muffler Assembly - Inspection

4/94

Requirement: CANCELLED.

Background: The requirements of Piper Service Bulletin No. 691 are now adequately reflected in the Piper Cherokee Service Manual Section 111, Para 3-10.