

Piper PA-28 Series Aeroplanes

AD/PA-28/90

Nose Gear Drag Link

10/94

Applicability:	Model	Serial Numbers
	PA28R-180	28R-30004 through 28R-7130013
	PA28R-200	28R-35001 through 28R-7635545
	PA28R-201	28R-7737001 through 28R-7837317
	PA28R-201T	28R-7703001 through 28R-7803373
	PA28RT-201	28R-7918001 through 28R-8218003
	PA28RT-201T	28R-7931001 through 28R-8231009
Requirement:	Incorporate Nose Landing Gear Modification Kit, Piper Part No. 764-377. Accomplish this action in accordance with the procedures and sketches included with the instructions to the above referenced kit. <i>Note 1: The modification kit referenced above consists of a close tolerance bolt (NAS464P4-27), four bearings, and other associated hardware for installation on the drag link assembly. This NAS464P4-27 bolt replaces the AN4-20 bolt used to connect the upper and lower drag links.</i> <i>Note 2: FAA AD 94-14-14 Amdt 39-8962 and Piper Service Letter 988 refer.</i>	
Compliance:	Within 100 hours time in service after 15 September 1994.	
Background:	The FAA received reports of collapsed nosegear on the affected aircraft. In particular, these reports reveal failure of the bolt (AN4-20) connecting the lower drag link of the nosegear to the upper drag link.	