

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-32/44.

---


### Piper PA-32 (Cherokee Six) Series Aeroplanes

**AD/PA-32/44**                      **Throttle Linkage Bolt - Replacement**                      **10/2008**

Requirement:    CANCELLED.

This AD is cancelled on 25 September 2008.

Background:      This unique Australian AD specified replacement of a bolt in the throttle linkage in accordance with Piper SB No. 537. Compliance was required within 100 hours time in service after April 1977. The AD is no longer required.



Charles Lenarcic  
Delegate of the Civil Aviation Safety Authority

15 August 2008