

Piper PA-34 (Seneca) Series Aeroplanes

---

**AD/PA-34/3  
Amdt 1**

**Induction Air Box Valve - Inspection**

**9/72**

Applicability: Model PA34-200 with S/Nos. 34-E4 and 34-7250001 to 34-7250360 and 34-7350001 to 34-7350074 not modified in accordance with Piper SB No. 374.

Document: Piper SB No. 358.

Compliance: Within 100 hours time in service after 29 September 1972 and there-after at intervals not exceeding 100 hours time in service.