
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-34/4.

Piper PA-34 (Seneca) Series Aeroplanes

AD/PA-34/4

**Stabilator - Inspection and
Drilling of Drain Holes**

11/2008

Requirement: CANCELLED.

This AD is cancelled on 23 October 2008.

Background: This unique Australian AD specified Piper SL No. 615 which called for once-only inspection of the number and location of drain holes in the stabilator and, if inadequate, drilling of drain holes in the required locations. Compliance was required within 100 hours time in service after September 1972. The AD is no longer required.



David Villiers
Delegate of the Civil Aviation Safety Authority

9 September 2008