

Piper PA-34 (Seneca) Series Aeroplanes

---

**AD/PA-34/6  
Amdt 2**

**Exhaust System - Inspection**

**9/73**

Applicability: Model PA34-200 S/Nos. 34-E4, 34-7250001 and higher, fitted with exhaust stack assemblies P/N 96465-00 and 96466-00.

Requirement: PART 1

Inspect the exhaust system for cracks or broken pipes in the vicinity of all welded areas and feel for any looseness of the pipes in the vicinity of mounting flanges.

*Note: The above inspection may be performed and certified by the pilot.*

PART 2

Carry out inspection in accordance with Piper SB No. 373A or FAA AD 73-14-12. In addition remove the cabin air heater shroud and inspect the exhaust pipe for chafing marks made by the shroud. Also inspect cowls for chafing marks.

Compliance: Part 1 - At each daily inspection.

Part 2 - Within 10 hours time in service after 28 September 1973 and thereafter at intervals not exceeding 25 hours time in service.