

Piper PA-34 (Seneca) Series Aeroplanes

AD/PA-34/9

Rudder Servo Trim Tab - Inspection

6/73

Applicability: All models not incorporating modification kit P/N 760 800 V.

Document: Piper SB No. 390A.

Compliance: Within 10 hours time in service after 25 June 1973 and thereafter at intervals not exceeding 100 hours time in service.