
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-34/13.


Piper PA-34 (Seneca) Series Aeroplanes

AD/PA-34/13 Propeller Damper Screws - Replacement 11/2008

Requirement: CANCELLED.

This AD is cancelled on 23 October 2008.

Background: This unique Australian AD specified replacement of propeller damper screws in accordance with Piper SL No. 706. Compliance was required within 100 hours time in service after July 1974. The AD is no longer required.



Charles Lenarcic
Delegate of the Civil Aviation Safety Authority

11 September 2008