

Piper PA-34 (Seneca) Series Aeroplanes

AD/PA-34/18

**Quick Disconnect Seat Retention
Mechanism - Inspection**

12/75

Applicability: Model PA-34-200 with S/Nos. 34-7250001 to 34-7450220.

Model PA-34-200T with S/Nos. 34-7570001 to 34-7570054.

Document: Piper SL No. 763.

Compliance: Within 100 hours time in service after 30 January 1976.