

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PA-34/23.

---

### Piper PA-34 (Seneca) Series Aeroplanes

**AD/PA-34/23**


**Induction, Air Box, Filter  
Locator Clips - Replacement**

**11/2008**

Requirement: CANCELLED.

This AD is cancelled on 23 October 2008.

Background: This unique Australian AD specified replacement of induction, air box, and filter locator clips in accordance with Piper SB No. 542. Compliance was required within 100 hours time in service after May 1977. The AD is no longer required.



Charles Lenarcic  
Delegate of the Civil Aviation Safety Authority

11 September 2008